



Workshop 4


Replacing Cabin Filter

Terrano II 2.7tdi SE+ Year 2000

- Remove the two screws from the hinges on the lower edge of the glove box.
- Remove the two screws on the left-hand panel, there are actually three but you cannot get to the third one yet.
- Pull off a small amount of the rubber door strip next to this panel.



- Now gently ease the left-hand panel towards the door....there is still one screw still holding it so don't over do it.
 - Tilt the glove box door up at one end , this will allow you to remove the door with a bit of jiggling of the left hand panel.
 - With the glove box door now removed the third screw in the left-hand panel is now accessible and should now be removed.
-
- Remove the three screws from the steel cross bar.
 - Lift the cross bar from the lower edge up towards yourself and unhook from the two hangers.
 - Remove the single screw from the filter cover and the slide the small panel downwards to reveal the filter.
 - Now pull the filter out of its housing.



One blocked Filter



- Fit a new filter and reassemble by reversing the above sequence.

**Written and produced
By Wilf**